


HT Instruction

CONTRAINDICTION:

HT: Not suggested to fabricate 3 units continually missing bridge of posterior teeth.

SINTERING CURVE

Temperature



To achieve expected quality, the sintering curves must be followed.